Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Diahatsu DL280 Head

When a world-wide marine company sent us a Diahatsu DL280

cylinder head for repair, close inspection revealed it had cracks from the valve cages to the flame face, and also the water passageway holes were badly corroded.

We undertook repairs by way of our Lloyds approved fusion welding procedures before NDT inspection to ensure repairs were sound, then machined back to correct tolerances and fitted spare parts. This was followed with a thorough cleaning and painting, before the head was witnessed under pressure by Lloyds for certification purposes prior to dispatch.

For any Marine Cylinder Head repairs

contact us for a free survey/ quotation.

12 months warranty on all our repairs.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedures
- Machining Facilities
- Fitting of Spares
- Classification Certificates

Breathing new life into damaged cast iron components

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: + 44 (0) 1530 274646 Fax: + 44 (0) 1530 274647 Email: info@slinden.co.uk