



Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Cast Iron Window Balcony



When a query came in to us for repair and restoration of an ornate cast iron balcony, our engineer attended an on site inspection before bringing back to our workshop.

We found missing scrolls and bars as well as general cracks that needed welding, and modifications would also be required to the feet and wall fixings to allow for safer installation into the base and wall.



We carried out welding repairs by way of our Lloyds approved fusion welding procedures, giving a repair as strong if not stronger than the original material, also manufacturing the missing parts and making the modifications where necessary.



The welds were then ground up to the correct profile to match existing shape before full crack testing. After the welding and inspection process, the railings

were shot blasted and primer applied followed by a gloss top coat.

For any Architectural Restorations please call for a survey/ quotation.



- On Site Inspection/Quotation
- Lloyds Welding Procedures
- Full Crack Detection
- Full Shot Blasting
- Recasting Service
- Painting as Required
- 2 Year Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646 Fax: +44 (0) 1530 274647 Email: info@slinden.co.uk