



Slinden Services Ltd

Cast Iron Welding and Engineering

INDUSTRIE 6D7 HDM



Two Industrie Marine Cylinder Heads were received for repairs at our works. After close inspection, MPI testing revealed that the heads had suffered from 'pitting' and excessive fretting on the high pressure sealing ring and extensive cracks from the Injector to the Valve Seat pocket.



This area was ground back to sound material, followed by our approved Fusion Welding Procedure. The repaired area was then NDT inspected to ensure a sound repair had been undertaken. Machining back to correct tolerances, spare parts were fitted, followed by thorough cleaning and painting ready for dispatch. The heads were witnessed under Lloyds class

for certification purposes.

For any Marine Cylinder head repairs contact us for a free survey/quotation.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedures
- Machining Facilities
- Fitting Of Spares
- Classification Certificates
- 12 Months Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk