



Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Victorian Garden Urn



We received an enquiry from a customer whose Victorian Garden Urn was in need of repairs - the bowl section was lying close to the ground as it had broken away from its stand due to worn components, and a piece had been broken off the rim. The urn was brought to our Derbyshire workshop where it was blasted and checked for any other defects. Weld repairs were undertaken to the missing section using our Lloyds approved welding procedures for cast iron, before the manufacturing of a new centre plate and brace which would join all the components together as intended!



The urn was then given a coat of red oxide primer, grey undercoat and a top coat of high-build white gloss. And, as the last picture shows - restored to its former glory!



For any Architectural Restorations, please call us for a survey/quotation.

- Lloyds Welding Procedures
- Full Crack Detection
- Full Shot Blasting
- Recasting if needed
- Painting as Required
- 2 Year Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: info@slinden.co.uk