



Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Village Water Pump



We were contacted by a customer who had acquired an old cast iron village pump which was in need of some TLC. The foot of the pump had part of the base flange missing, and the top of the pump was short of its original cap and finial!



Fortunately, the customer was given a cap on loan, so that a pattern could be made and a new one cast by our preferred foundry (alongside a new finial), whilst we carried out repairs to the base flange by way of our fusion welding procedure. This was followed by the repairs

being ground to shape, shot blasting, and all finished parts painted with a red oxide primer before customer collection.



“My pump looks excellent. It’ll be put up soon and I’ll paint it – it’s been admired by my friends for a job perfectly done - thanks again”.

For any Architectural Restorations, please call us for a survey/quotation.

- Lloyds Welding Procedures
- Full Crack Detection
- Full Shot Blasting
- Recasting if needed
- Painting as Required
- 2 Year Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646 Fax: +44 (0) 1530 274647 Email: info@slinden.co.uk