



Slinden Services Ltd

Cast Iron Welding and Engineering

Fi-Fi Pump Volute Casings



A world-wide Marine company requested our urgent specialized services whilst in dry dock to repair and recondition two fire pumps which had sustained severe cavitation in the main volute casings.

This area was ground back to sound material and subsequently welded using our Lloyds approved welding procedures for Cast Iron.

The repaired area was then NDT inspected to ensure a sound repair had been undertaken then machined back to correct tolerances, followed by thorough cleaning and coating with ceramic polymers ready for dispatch to meet with the ships engineers for re-installation on board the vessel.

The repairs were carried out within the vessels dry dock allotted time to avoid any delays.

For any Marine engine repairs - contact us for a free survey/ quotation.

12 months warranty on all our repairs.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedures
- Machining Facilities
- Fitting Of Spares
- Classification Certificates
- 12 Months Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk