



Slinden Services Ltd

Cast Iron Welding and Engineering

MAN ALFA U28



A batch of 12 MAN Alfa U28 Cylinder Heads were received at our works - very badly damaged and cracked from the Injector to the Valve Seat pocket.

This area was ground back to sound material and followed by our approved Fusion Welding Procedure.

The repaired area was then NDT inspected to ensure a sound repair had been undertaken then machined back to correct tolerances, spare parts were fitted, followed by thorough cleaning and painting ready for dispatch overseas to meet with

the ships engineers for re-installation on board ship.

The heads were witnessed under pressure test before dispatch by Bureau Veritas for certification purposes.

For any Marine Cylinder head repair contact us for a free survey/quotation.

12 months warranty on all our repairs.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedures
- Machining Facilities
- Fitting Of Spares
- Classification Certificates
- 12 Months Guarantee



*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk