



Slinden Services Ltd

Cast Iron Welding and Engineering

Peter Pan Statue



As part of preserving our history and culture, Slinden Services carried out the repair and restoration of an historic statue from a local private estate - 'Peter Pan' which was badly cracked down the back of the statue, due to frost and weather conditions in the UK.

The Cast Iron statue was transported to our factory in Derbyshire for careful repairs using our Fusion Welding Procedure.

This included preparation of the damaged area by removal of a large piece of iron and subsequent welding to this area.

This was a delicate process due to the nature of this item and also its historic value.

After the repair process, 'Peter' was painted and carefully transported back to the Trustees of the park in Derby who kindly sent us the final photograph of the statue back in pride of place for future generations to admire.

For any Architectural Restorations—please call us for a survey/quotation.

- On Site Inspection
- Lloyds Welding Procedure
- ASME IX Welding Codes
- Full Shot Blasting
- Painting As Required
- Re-Casting Service
- 2 Year Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk