



Slinden Services Ltd

Cast Iron Welding and Engineering

Zetor Engine



A Zetor Engine was in need of some T.L.C when it arrived at our factory.

As you can see from the photographs this block was badly frost damaged - but with our lock and pin procedures we managed to *breathe new life* into this engine, that otherwise would have been beyond repair.

The frost damaged water jacket was removed, this enabled us to manufacture a new side plate which was applied by our Lock and Pin method for repair.

This repair was a great success!

It has now given our client a fully reconditioned component which was a fraction of the new replacement cost!

For any Metal Stitching Repairs contact us for a free survey/ quotation. On site service available!

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Machining Facilities
- All Work Guaranteed



*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk