



# Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

## Ornate Window Grille



We were approached by a customer with an ornate cast iron window grille that had shattered meaning lots of the finer details had been broken off, needing our help to repair and restore it back to its former glory!



He built a customised box for the carriage of the item, and sent it to our Derbyshire workshop, taping the components into position as best could, which would help us to jigsaw the ornate pattern of the grille back together when using our Lloyds approved fusion welding procedures for cast iron, giving a repair as strong if not stronger than the original

material. The repairs were then ground to match existing profiles, crack tested, and blasted before a coat of red oxide primer and black undercoat. This was a delicate process due to the nature of the item.



The grille was then repacked in its box ready for the journey home to our customer, who would be repainting and rehangng it.



*"Many thanks for doing such an excellent job. Here's the window grille back in it's door."*

For any Architectural Restorations, please call us for a survey/quotation.

- Lloyds Welding Procedures
- Full Crack Detection
- Full Shot Blasting
- Recasting if needed
- Painting as Required
- 2 Year Guarantee

*Breathing new life into  
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: [info@slinden.co.uk](mailto:info@slinden.co.uk)