



Slinden Services Ltd

Cast Iron Welding and Engineering

Napier Turbo Casing



A Multi National Marine Company requested our services to repair and recondition a Marine Turbo Casing which had sustained a fatigue fracture and was leaking coolant water.

This area was ground back to sound material and subsequently welded using our Lloyds approved welding procedure for Cast Iron.

The repaired area was then NDT inspected to ensure a sound repair had been undertaken then machined back to correct tolerances, followed by thorough cleaning and painting ready for dispatch to meet with the ships engineers for re-installation on board ship.

The Casing was witnessed under pressure test before dispatch by Lloyds Register for certification purposes.

For any Marine engine repairs - contact us for a free survey/quotation.

12 months warranty on all our repairs.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedures
- Machining Facilities
- Fitting Of Spares
- Classification Certificates
- 12 Months Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk