



# Slinden Services Ltd

Cast Iron Welding and Engineering

## St James Hotel



Several Cast Iron Railings were damaged at an impressive hotel in London. This damage was caused by a lorry reversing into the railings.

After an on site inspection by one of our Engineers, the railings were removed from site and carefully transported back to our factory in Derbyshire to avoid any further damage.



Once the railings were back at the workshop, one section was carefully put back together using our approved Fusion welding procedure. This section was then used as a

'pattern' to re-cast other sections that were excessively broken.



Once the new sections were re-cast, they were then undercoated and painted and returned to site to be refitted by our Engineers.

- On Site Inspection
- Lloyds Welding Procedure
- ASME IX Welding Codes
- Full Shot Blasting
- Painting As Required
- Re-Casting Service
- 2 Year Guarantee

*Breathing new life into  
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: [info@slinden.co.uk](mailto:info@slinden.co.uk)